



10/072,697

gfc

PATENT
Customer No. 22,852
Attorney Docket No. 06530.0342

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: 6,869,436 B2)
Inventor: Jeffrey M. WENDLANDT)
Issue Date: March 22, 2005)
For: SURGICAL CLIP WITH A SELF-)
RELEASING FLUID RESERVOIR)

Certificate
MAY 31 2005
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Pursuant to 35 U.S.C. § 254, and 37 C.F.R. § 1.322, this is a request for a Certificate of Correction in the above-identified patent. The mistakes identified in the appended Form occurred through the fault of the Patent Office, as clearly disclosed by the records of the application which matured into this patent.

Two (2) copies of PTO Form 1050 are appended. The complete Certificate of Correction involves one (1) page. Issuance of the Certificate of Correction containing the correction is earnestly requested.

Respectfully submitted,

FINNEGAN, HENDERSON, FARABOW,
GARRETT & DUNNER, L.L.P.

Dated: May 25, 2005

By: Leslie I. Bookoff
Leslie I. Bookoff
Reg. No. 38,084

JUN 01 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. U.S. 6,869,436 B2
DATED: March 22, 2005
INVENTOR: Jeffrey M. WENDLANDT

It is hereby certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 1, line 59, "modem" should read --modern--.

Claim 18, col. 8, line 50, "farther" should read --further--.

Claim 19, col. 9, line 3, "atop" should read --a top--.

Claim 20, col. 10, line 21, "in" should read --includes--.

MAILING ADDRESS OF SENDER

Finnegan, Henderson, Farabow,
Garrett & Dunner, L.L.P.
901 New York Avenue, N.W.
Washington, D.C. 20001-4413

Patent No. U.S. 6,869,436 B2

No. of additional copies
@ .30¢ per page

JUN 01 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. U.S. 6,869,436 B2
DATED: March 22, 2005
INVENTOR: Jeffrey M. WENDLANDT

It is hereby certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 1, line 59, "modem" should read --modern--.

Claim 18, col. 8, line 50, "farther" should read --further--.

Claim 19, col. 9, line 3, "atop" should read --a top--.

Claim 20, col. 10, line 21, "in" should read --includes--.

MAILING ADDRESS OF SENDER

Finnegan, Henderson, Farabow,
Garrett & Dunner, L.L.P.
901 New York Avenue, N.W.
Washington, D.C. 20001-4413

Patent No. U.S. 6,869,436 B2

No. of additional copies
@ .30¢ per page

JUN 01 2005